






1





B1  $\phi 8 \times 28$ x14


F12  x5


M1  $\phi 15 \times 12 \text{mm}$ x31


Y17  x4


B2  $\phi 8 \times 50$ x4




P13  3,5x13 x20

T1  5x39mm x31









S8  4x13 x8

C5  $\phi 5$ x4























W1  x8



2



3



4

