




BREGI K 2 D



Instrukcja montażu
Assembly instructions



No.	Stc.	L	W	T
1	1	900	400	22
2	1	856	377	16
3	1	1000	400	22
4	1	1000	400	22
5	1	453	377	16
6	1	453	377	16
7	1	856	377	16
8	1	495	370	16
9	1	345	370	16
10	1	856	60	16
11	1	467	348	16
12	1	484	500	16
13	1	954	366	3
14	1	954	516	3






CAUTION
STICKING PINS HOW TO
DRAWING

ACHTUNG
DAS FESTHALTEN PINS
HOW TO ZEICHNUNG

UWAGA! WAŻNE!
KOLKI WBIJAĆ JAK NA
PONIŻSZYM RYSUNKU

W KRAWĘDZ ELEMENTU
11.0 mm

UWAGA!
ATTENTION!



Wypoziomować miejsce docelowe
Level the target
Nivellieren das Ziel

