




















FINEZJA - F3

Szafa 3 drz.




1  x28	2  x28	3  8x35 x50	4  4x22 x3	5  x55	6  x4
7  x8	8  3,5x16 x32	18  x8	10  x3	11  x1	12  x1
13  x12	14  H-2 x8	15  H-0 x4	16  H-11 x4	17  x16	

Czas mont. - 100 min.







FINEZJA - F3





Szafa 3 drz.








1






2





4






5

2



x12

6








2







x8


7





- | | | |
|----|--|--------------|
| 6 |  | x4 |
| 8 |  | 3,5x16
x8 |
| 11 |  | x1 |
| 3 |  | 8x35
x14 |

- | | | |
|---|---|-----|
| 5 |  | x55 |
|---|---|-----|





4 4x22 x3	13 x12
10 x3	8 3,5x16 x24



7 x8

