






















LORIN


R-2








 M 28x	 M1 28x	 F 4x	 U 2x	 2kpl. PK-0H35-350						
 D 1x	 H 1x	 Z1 6x	 PZ 6x	 E1 16x	 D2 8x	 D3 8x	 D4 16x	 D5 4x	 K 28x	
 WS 2x	 N 4x	 T 2x	 W 2x	 S 10x	 ZM 28x	 G 36x	 KL 1x	 SL 2x	 PS 1x	



1

	
M	K
8x	8x




2


		
T	M	K
1x	4x	4x




3





4





5

		
D4 2x	W 1x	M1 10x




6



E1 4x




7




8




9




10




11




12





13




	
D4	Z1
6x	3x

14




	
U	D3
1x	4x


15




16




17




18





19






20




21




22











23







24




25





26




regulacja!
regulation!
verordnung!




27





±2mm



±2mm



±2mm



CLICK