


































K30  30	T1  20	M1  20	X  20	STB  4	UM  1	E5x13  8	M22  1
KF  2	W4x16  4	MF  5	SM  5				
Q  1	4.0x30  1	ZP  2	PZ  2				




















 M1	 K30	 T1	 E5x13	 KF	 Q	 RL
4	6	4	4	2	1	2








A=B



90°



	SM
STB	
4	5

A=B

STB

SM

M22



1

X



20

UM



1

9

10

UM

M22

Click

Click